

Max. working pressure : 8 bar (116 psi)

Max lifting weight : 10300 kg (22701 lb)

Max air volume : 28,3 L (6,2 imp. gal.)

Max lifting height : 210 mm (8,2")

8 barHeight
(mm)Weight
(kg)

50



7800

100



4500

150



2000

210



400

! STORAGE AND USE INSTRUCTIONS FOR LIFTING BAGS !

- Place the lifting bag under load to be lifted
- When using the bag do not pull the coupling to avoid the feed's traction
- Respect the 8 bar max. pressure
- Be sure that the surface in direct contact with the lifting bag does not present any points that could cause the rupture
- Do not inflate a lifting bag un-loaded
- Store the lifting bag sheltered from light
- Please refer to the detailed instructions

CE

EN 13731 : 2007

Prod. 01/24

