

Max. working pressure : 8 bar ( 116 psi )

Max lifting weight : 3500 kg ( 7714 lb )





Max air volume : 5,16 L ( 1,13 imp. gal. )

Max lifting height : 100 mm ( 4" )

**8 bar**

**Height  
(mm)**

**Weight  
(kg)**

25	50	75	100
			
<b>3200</b>	<b>2200</b>	<b>1200</b>	<b>650</b>

## ! STORAGE AND USE INSTRUCTIONS FOR LIFTING BAGS !

- Place the lifting bag under load to be lifted
- When using the bag do not pull the coupling to avoid the feed's traction
- Respect the 8 bar max. pressure
- Be sure that the surface in direct contact with the lifting bag does not present any points that could cause the rupture
- Do not inflate a lifting bag un-loaded
- Store the lifting bag sheltered from light
- Please refer to the detailed instructions

CE

**EN 13731 : 2007**

Prod. 01/24

