

Max. working pressure : 8 bar ( 116 psi )

Max lifting weight : 37000 kg ( 81548 lb )

Max air volume : 210 L ( 46,2 imp. gal. )

Max lifting height : 420 mm ( 16,5" )

**8 bar**

Height  
(mm)

Weight  
(kg)

50



100



200



300



420



37000

27000

14000

5000

2000

**! STORAGE AND USE INSTRUCTIONS FOR LIFTING BAGS !**

- Place the lifting bag under load to be lifted
- When using the bag do not pull the coupling to avoid the feed's traction
- Respect the 8 bar max. pressure
- Be sure that the surface in direct contact with the lifting bag does not present any points that could cause the rupture
- Do not inflate a lifting bag un-loaded
- Store the lifting bag sheltered from light
- Please refer to the detailed instructions

